

17 Jan 44 (At Laverton) *“Leading edge of starboard tail plane of Lockheed Ventura A59-14 piloted by S/L Kemp, slightly damaged when hatch over pilots compartment blew out in test dive. Nil injury to personnel.”* 1 AD (T&F) A50

5 Feb 44 *“Aircraft A59-14 Ventura B34 arrived.”* 13 Sqn A50

6 Feb 44 *“Received 13 Sqn ex1 AD.”* Status card

13 Feb 44 F/O LE Coleman Can - Can SACO Co-op P40's B25's Bowden Log 14

15 Mar 44 *“Allotted 1 AD ex 13 Sqn for necessary repairs.”* Status card

As of 1 Apr 44 *“All B34 aircraft have been grounded pending arrangements for complete overhaul.”* WSR

5 May 44 *“Ventura aircraft B34 A59-14 departed on allotment to No 2 AD this aircraft being the last of the B34's held by this Squadron.”* 13 Sqn A50

5 May 44 *“Received 2 AD ex 13 Sqn for report.”* Status card